
4680 Dogwood Drive existing conditions

Slope/Plant damage from lack of water retention







Elevation view of slope




View of River from Base of slope

Looking west from lower bank path, (slope on the right)







1B

